




## APPENDIX



#34 are disclosed as being support wires and are not configured to conduct electrical current. The support wires which are recited in claim 4 read on these wires. These wires therefore cannot be considered to anticipate the claimed "at least one lead rod" in claim 1.

Further, there are no filaments on either side thereof and therefore do not meet the claimed requirement that "each lead rod has two filaments located on essentially diametrically opposite side thereof"

# 26 are disclosed as electrically conductive lead-in conductors or wires. As clear from Fig. 2 (below) neither of these wires have filaments on opposite sides thereof and therefore do not meet the claimed requirement that "each lead rod has two filaments located on essentially diametrically opposite sides thereof"



**FIG. 2.**

